

Campaign ID Number: **79V261000**

**Vehicle Make / Model:** FORD / BRONCO

**Model Year(s):** 1980

**Manufacturer:** FORD MOTOR COMPANY

**Mfr's Report Date:** 12/18/1979

**Campaign ID Number:** 79V261000

**Component:** POWER TRAIN:AUTOMATIC TRANSMISSION:LEVER AND LINKAGE:COLUMN SHIFT

**Potential Number of Units Affected:** 80000

**Summary:**

THE PARKING PAWL ACTUATING ROD IN THE TRANSMISSION MAY HAVE AN INSUFFICIENT OR CRACKED WELD. THIS CAN CAUSE THE PARK CAM END TO SEPARATE FROM THE ROD ITSELF, PREVENTING THE PARKING PAWL FROM ENGAGING THE PARKING GEAR WHEN THE SELECTOR IS PLACED IN THE PARK POSITION.

**Consequence:**

**Remedy:**

DEALER WILL REPLACE THE DEFECTIVE PARKING PAWL ACTUATING ROD FREE OF CHARGE.